



SYSTEMS-LINK WIRING DIAGRAM




COMM INDICATOR
PWR INDICATOR

LEDS
FEED THRU
FEED THRU
GAUGES

POWER

UP TO 8 RESISTORED LED WARNING LAMPS



UP TO 2 SPEEDOMETERS AND 2 TACHS
SPEEDO - Pins 13 and/or 14
TACH - Pins 11 and/or 12



UP TO 10 2 in. GAUGES
Pins 1 to 10



PIN 9 - GAUGE GND

PIN 4 - +12/24V OUTPUT TO GAUGES AND LEDES

PIN 5 - SWITCHED INPUT

PIN 10 - GND

5 AMP FUSE